



# IMPLEMENTATION OF RELIABILITY ENGINEERING PRINCIPLES IN PISTON ROD MANUFACTURING

# INTRODUCTION OF PRESENTER

Name : Rafay Hasan

Roll No : ME-009

Company Name : Agriauto Industries Limited

Course : Reliability Engineering (RE-539)

Institution : NED University



# AGENDA

BASICS OF SHOCKS & STRUTS

FUNCTIONS OF SUSPENSION SYSTEMS

COMPONENTS OF STRUTS


RELIABILITY IN MANUFACTURING

QUALITY CONTROL METHODS

CASE STUDY AND RECOMMENDATIONS









# KEY FUNCTIONS

- Maximizes tire-road contact
- Provides steering stability
- Ensures comfort by absorbing shocks
- Supports vehicle weight efficiently
- Isolates the body from road vibrations




# KEY PARTS

- Piston Rod
- Outer & inner Tubes
- Eye rings
- Brackets
- Valves
- Oil
- Gas (nitrogen)
- Rubber Bush



# PDCA CYCLE IN IMPROVEMENT

- **Plan:**
  - Identify problems or areas for improvement
  - Develop objectives and processes required
- **Do:**
  - Implement the plan on a small scale
  - Collect data for analysis
- **Check:**
  - Review and analyze the results
  - Compare outcomes against objectives
- **Act:**
  - If successful, implement on a larger scale
  - If not, refine the plan and repeat the cycle





# QUALITY CONTROL METHODS

- Dimensional and surface finish inspection
- Material testing and non-destructive testing (NDT)






# QUALITY CONTROL METHODS

- Functional testing of damping force






# AIL Shock Absorber Damping Force Tester

STOP

Element Drive Position Reset **Speed Test** Report List Part Selection Data Graphics

Ver. 2015.01.28 Daily Tech

Damping Force vs. Position



OK

FINISHED

REFERENCE NOT FOUND

Max. Recoil 1

252.3

-183.2

Max. Recoil 2

70.8

Max. Comp 2

-78.1

DAMPING START M600

DAMP END M602

Gas

1.6

Temperature

25

PLC Repy M601

SERVO FRW

Stroke (mm)

50

PreSpeed PreCycle

0.3

2

Model (less than 25 chars)

:\testdata\model\Y4J RR

Identified Number

20

PROGRAM ON

Speed Selection

2

Speed Cycle

0.3

2

0.1

2

0

3

Recoil R+ R- Comp C+ C-

269

56

56

217

56

56

66

37

37

90

47

47

0

0

0

0

0


0

APPEND

Save Filepath

d:\testdata\20241125113542

Tab Control



# CASE STUDY OVERVIEW

- **Problem Identified** : Rear shock absorber with noise issues and low recoil
- **Details of Failure : Parts Date Code:** 9122 (2nd Week of Date : XXXXX)
- **Engraving:** AA141219B225
- **Mileage:** 1121 KM




Received Condition



# DEFECTS OBSERVED

- Riveting non-conformance (Diameter and Height out of spec)
- Part missed during inspection
- Grooving tool offset during CNC machining
- Forceful insertion by assembly operator



## **Riveting observed NG:**

Diameter = 9.387 mm (7.7 ~ 8.3 mm)

Height = 1.51 mm (0.8 ~ 1.4 mm)



# PROBLEM CLARIFICATION

## WHAT

- Recoil low observed in damping force testing
- Riveting observed NG

## WHERE

- Reported from the field warranty

## WHEN

- Problem reported on Date : XXXX

## WHO

- PSMCL PID Department (Warranty)

## HOW

- Part handed over physically during PSMC visit @ AIL ( Date : XXXXXXXXXXXX )

# FAILURE MODE AND EFFECTS ANALYSIS (FMEA)


#	Failure Mode	S	O	D	RPN	Action Taken
1	Tool offset during machining	4	3	4	48	CNC calibration, operator training
2	Forceful insertion causing damage	5	2	5	50	Revised assembly process
3	Missed inspection of critical dimensions	5	3	5	75	Additional checks, new gauge

## Risk Levels

- Low (RPN 1-30), Moderate (31-75), High (>75)


# PARETO ANALYSIS

Defect Code	Description	Weight
Def1	Missed inspection	10
Def2	Tool offset during machining	9
Def3	Forceful insertion of assembly	8
Def4	Riveting non-conformance	7
Def5	Human error	8
Def6	Others	6



# ISHIKAWA (CAUSE AND EFFECT) DIAGRAM

16





# POINTS OF OCCURRENCE AND DETECTION

## Point of Occurrence


- Piston Rod Machining: Tool offset leading to incorrect groove location

## Point of Detection #1

- Damping Force Testing: Recoil low observed, but part passed mistakenly

## Point of Detection #2

- Final Inspection: Missed detection of machining defect



# RESULTS AND IMPROVEMENTS

## Quality Improvements

- Reduction in defects and warranty claims
- Enhanced product reliability

## Process Enhancements

- Improved inspection procedures
- Better operator performance through training





# COUNTERMEASURES IMPLEMENTED

## **Additional Checks**

- Supervisor verification on DFT results

## **Gauge Fabrication**

- Spacer-type gauge to detect offset rods

## **Operator Training**

- Retraining assembly operators
- Emphasis on proper assembly techniques

## **CNC Calibration**

- Regular maintenance and calibration schedules
- 



# COUNTERMEASURES IMPLEMENTED

## **Additional Checks**

- Supervisor verification on DFT results

## **Gauge Fabrication**

- Spacer-type gauge to detect offset rods

## **Operator Training**

- Retraining assembly operators
- Emphasis on proper assembly techniques

## **CNC Calibration**

- Regular maintenance and calibration schedules
- 



# KEY RECOMMENDATIONS

- Simplify and clarify work instructions.
- Conduct regular training and refreshers.
- Implement strict calibration and maintenance schedules.



# THANK YOU

## QUESTIONS & ANSWERS